

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	3705	385/129,130,131.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
2	BRS	L2	14012	planar\$5 same waveguide\$1	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
3	BRS	L3	3776	((scarific\$4 photoresist\$4 photo adj1 resist\$4 dielectric\$4) near7 clad\$4)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
4	BRS	L4	3789	((scarific\$4 photoresist\$4 photo adj1 resist\$4 dielectric\$4) near7 clad\$5)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
5	BRS	L5	2304	(remov\$4 etech\$3) near6 clad\$5 same etch\$4	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05

	Comments	Error Definition	Errors
1			
2			
3			
4			
5			

	Type	L #	Hits	Search Text	DBs	Time Stamp
6	BRS	L6	103	L2 and L4 and L5	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
7	BRS	L7	101	L6 and L3	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
8	BRS	L8	31	L1 and L7	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
9	BRS	L9	24	L8 and (etch\$3) near6 clad\$5 same core\$1	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05
10	BRS	L10	12	L9 and ((scarific\$4 photoresist\$4 photo adj1 resist\$4) near7 clad\$5)	US- PGPUB; USPAT; EPO; JPO; DERWEN T	2006/09/19 12:05

	Comments	Error Definition	Errors
6			
7			
8			
9			
10			

	Type	Hits	Search Text
1	BRS	1	10/727201
2	BRS	0	S1 and embodiment\$3
3	BRS	0	S1 and embodiment\$3
4	BRS	0	S1 and embodiments
5	BRS	0	S1 and embodiment\$1
6	BRS	1	10/727201
7	BRS	1	S6 and (core\$1 clad\$4 photo photoresist\$3 higher lower portion\$1 expos\$4 polish\$4)
8	BRS	12421	planar\$5 same waveguide\$1
9	BRS	3379	((scarific\$4 photoresist\$4 photo adj1 resist\$4 dielectric\$4) near7 clad\$4)
10	BRS	3390	((scarific\$4 photoresist\$4 photo adj1 resist\$4 dielectric\$4) near7 clad\$5)
11	BRS	7747	(remov\$4 etech\$3) near6 clad\$5
12	BRS	2083	(remov\$4 etech\$3) near6 clad\$5 same etch\$4
13	BRS	85	S8 and S10 and S12
14	BRS	83	S13 and S9
15	BRS	35	S14 and ((scarific\$4 photoresist\$4 photo adj1 resist\$4) near7 clad\$4)

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 18:40		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/24 18:42		
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/24 17:37		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/24 17:38		
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/24 17:39		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/24 18:19		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 17:24		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 11:17		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 17:29		
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 17:24		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 17:25		
12	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 17:26		
13	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:44		
14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
15	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:44		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9		S9
10		S10
11		S11
12		S12
13		S13
14		S14
15		S15

	Type	Hits	Search Text
16	BRS	35	("5805755" "20020106175" "6449417" "6434282" "6144779" "6022671" "5721801" "20030161571" "6813431" "20020108778" "6162655" "5879571" "20030108273" "6507681" "20030136760" "20020137247" "6818559" "6730988" "20050124173" "20050025408" "6621952" "20030201243" "20020092824" "6654532" "4827482" "20020097962" "20020039464" "20020028045" "6845184" "6785447" "6706546" "6690845" "6684007" "6611635" "6343171") .pn.
17	BRS	12421	planar\$5 same waveguide\$1
18	BRS	3390	((scarific\$4 photoresist\$4 photo adj1 resist\$4 dielectric\$4) near7 clad\$5)
19	BRS	2083	(remov\$4 etech\$3) near6 clad\$5 same etch\$4
20	BRS	85	S17 and S18 and S19
21	BRS	35	S16 and ((scarific\$4 photoresist\$4 photo adj1 resist\$4) near7 clad\$4)
22	BRS	35	S16 and S17 and S18 and S19
23	BRS	35	S16 and S18 and S19
24	BRS	1	10/727201
25	BRS	1	S24 and mask\$4
26	BRS	7	S23 and coplanar\$5
27	BRS	7	S19 and S26
28	BRS	1251	(second upper) adj1 (cladd\$4) near7 (etch\$4 remov\$4)
29	BRS	767	(lower first) adj1 (cladd\$4) near7 (etch\$4 remov\$4)
30	BRS	429	S28 and S29

	DBs	Time Stamp	Comments	Error Definition
16	US-PGPUB; USPAT	2005/10/25 19:43		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:44		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:22		
19	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:23		
20	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:15		
21	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:45		
22	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:48		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:48		
24	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:50		
25	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 19:54		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:06		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:03		
28	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:05		
29	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:05		
30	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:06		

	Errors	Ref #
16		S16
17		S17
18		S18
19		S19
20		S20
21		S21
22		S22
23		S23
24		S24
25		S25
26		S26
27		S27
28		S28
29		S29
30		S30

	Type	Hits	Search Text
31	BRS	119	S17 and S30
32	BRS	15	S31 and ((co adj1 planar\$5) coplanar\$5)
33	BRS	10	S32 not S21
34	BRS	489	revers\$3 adj1 mask\$4
35	BRS	9303	(remov\$4 etch\$3) near8 clad\$5 same etch\$4
36	BRS	8203	(remov\$4 etch\$3) near6 clad\$5 same etch\$4
37	BRS	8203	(remov\$4 etch\$3) near6 clad\$5 same etch\$4
38	BRS	187	S17 and S18 and S37
39	BRS	4	S34 and S38
40	BRS	74	S38 and ((scarific\$4 photoresist\$4 photo adj1 resist\$4) near7 clad\$5)
41	BRS	70	S40 and (etch\$3) near6 clad\$5
42	BRS	54	S40 and (etch\$3) near6 clad\$5 same core\$1
43	BRS	122	S42 anot (S22 S32)
44	BRS	27	S42 not (S22 S33)
45	BRS	2	("6922508" "20030007535" "20030007535") .pn.
46	BRS	2	("6922508" "20030007535" "6922508") .pn.
47	BRS	3	("6922508" "20030007535" "20030215189") .pn.
48	BRS	4	("6922508" "20030007535" "20030215189" "20040120675") .pn.
49	BRS	4	S48 and (planar\$5 coplanar\$5 co adj1 planar\$5)
50	BRS	2	"20030215189"
51	BRS	3287	385/129,130,131.ccls.

	DBs	Time Stamp	Comments	Error Definition
31	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:06		
32	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:07		
33	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:12		
34	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:12		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:13		
36	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:14		
37	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:14		
38	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:16		
39	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:16		
40	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:28		
41	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:23		
42	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:27		
43	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/25 20:25		
44	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 10:27		
45	US-PGPUB; USPAT	2005/10/26 11:14		
46	US-PGPUB; USPAT	2005/10/26 11:15		
47	US-PGPUB; USPAT	2005/10/26 11:16		
48	US-PGPUB; USPAT	2005/10/26 11:16		
49	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 11:49		
50	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:46		
51	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		

	Errors	Ref #
31		S31
32		S32
33		S33
34		S34
35		S35
36		S36
37		S37
38		S38
39		S39
40		S40
41		S41
42		S42
43		S43
44		S44
45		S45
46		S46
47		S47
48		S48
49		S49
50		S50
51		S51

	DBs	Time Stamp	Comments	Error Definition
52	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:46		
53	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
54	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
55	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
56	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
57	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:24		
58	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:26		
59	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:27		
60	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/09/19 12:05		
61	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 16:47		
62	US-PGPUB; USPAT	2005/10/26 17:12		
63	US-PGPUB; USPAT	2005/10/26 18:01		
64	US-PGPUB; USPAT	2005/10/26 18:02		
65	US-PGPUB; USPAT	2006/04/04 14:39		
66	US-PGPUB; USPAT	2005/10/26 18:06		
67	US-PGPUB; USPAT	2005/10/26 18:19		
68	US-PGPUB; USPAT	2005/10/26 18:22		
69	US-PGPUB; USPAT	2005/10/26 18:23		
70	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 18:40		
71	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 19:52		

	Errors	Ref #
52		S52
53		S53
54		S54
55		S55
56		S56
57		S57
58		S58
59		S59
60		S60
61		S63
62		S65
63		S64
64		S66
65		S61
66		S67
67		S68
68		S69
69		S70
70		S71
71		S72

	Type	Hits	Search Text
72	BRS	1	S64 and device
73	BRS	2	"20030215189" "20030161571"
74	BRS	2	S74 and (remain\$4 remnant\$4 sacrific\$5 expos\$5 remov\$5 etch\$5)

	DBs	Time Stamp	Comments	Error Definition
72	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/26 19:52		
73	US-PGPUB; USPAT	2006/04/04 14:39		
74	US-PGPUB; USPAT	2006/04/04 14:40		

	Errors	Ref #
72		S73
73		S74
74		S75

Day : Tuesday
Date: 9/19/2006
Time: 11:37:40

PALM INTRANET**Inventor Name Search Result**

Your Search was:

Last Name = MO KANG

First Name = JOON

Application#	Patent#	Status	Date Filed	Title	Inventor Name
10727201	Not Issued	71	12/03/2003	Method of fabricating optical waveguide devices with smooth and flat dielectric interfaces	MO KANG, JOON

Inventor Search Completed: No Records to Display.

Search Another: Inventor	Last Name	First Name
	<input type="text" value="MO KANG"/>	<input type="text" value="JOON"/>
		<input type="button" value="Search"/>

To go back use Back button on your browser toolbar.

Back to [PALM](#) | [ASSIGNMENT](#) | [OASIS](#) | Home page